

PS3083
 0041 Z40
 7116 5041 02
 180 1R7 039 43
 CIVUS 0.5 W/B
 5994 3424

PS3082 0047 SCN
 7116 5044 02
 7158 3009 60
 180 1R7 039 43
 CIVUS 0.5 W/B
 6641 6651

PS3081 0046 SCL
 7116 5044 02
 7158 3009 60
 180 1R7 039 80
 CIVUS 0.5 BR
 1346 1427

PS3080 0045 SCH
 7116 5041 02
 180 1R7 039 43
 CIVUS 0.5 W/B
 3102 3132

PS3079 0044 SCF
 7116 3154 02
 180 1R7 039 43
 CIVUS 0.5 W/B
 5002 5122

PS3078 0043 SCD
 7116 3154 02
 180 1R7 039 43
 CIVUS 0.5 W/B BR
 2156 2188

PS3077 0042 SCB
 7116 3154 02
 180 1R7 039 80
 CIVUS 0.5 BR
 2156 2188

0058 SBY
 7116 6563 02
 7172 5032 20
 180 1R7 039 80
 CIVUS 0.5 BR
 2055 2675

PS3076

0057 SBX
 7116 6563 02
 7172 5032 20
 180 1R7 039 43
 CIVUS 0.5 W/B
 1942 1060

PS3075

0041 %Z 1
 7116 2640 02

4.950mm' 4.561mm

PRPD	CHKD	APPD
<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>
Date 25/4/22	Date 26/4/22	Date 26/4/22

P F 3 0 2 9
 82161-BYC40/BYC20

REFER TO PROCESSING DRAWING
 加工図有り

MARK	DATE	NOTICE NO	CHANGE HEAD	APR	CHK	DRW

04-352800 / Detail Drawing of Center Slit/Join 		04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join	
04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join		04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join	
04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join		04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join	
04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join		04-352800 / Detail Drawing of Center Slit/Join L1 L2 L3 L4 04-352800 / Detail Drawing of Center Slit/Join	

DATE 2021/01/12 TIME 14:26 (2/8)